NRC Form 581			U.S. NUCLEAR REC	GULATORY COMMISSION
(12-81) 10 CFR 2-201	SAFETY II	NSPECTION		
1. LICENSEE		2 REGIONAL OFFICE		
Parker Industrial X-Ray Lab. Corp. 272 Governor Street East Hrtford, CT 06108		U. S. Nuclear Regulatory Commission Region I 475 Allendale Road King of Prussia, PA 19406		
3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S)		S. DATE OF INSPEC	TION
030-03768	06-01337-03		November	7, 1990
Licensi e: The ir spection was an examination of the activities. Regulatory Commissions (NRC) rules and regulation and representative records, interviews, with person 1. Within the scope of this inspection, no violation.	ons and the conditions of you nel, and observations by the	ur license. The inspection of	onsisted of selective e	xaminations of procedures
2. The inspector also verified the steps you have		ions identified during the la	ast inspection. We hav	ve no further questions on
		accordance with 10 CFR 19	9.11. was not properly pos	sted to indicate the presence 03(b), (c), (d), (e) or 34.42.
labeled to indicate the presence of radio		0		not performed at the proper
D. Records of 10 CFR E. Documents were not properly posted or		or License Condition Numb		ere not properly maintained.
F. Reports or notifications of				vere not made in accordance
DESIGNATE Cartified By:	SRIGINAL	REGION	w TO	/E:07
P012050 REG1 LII 06-0133	175 901107 C30 7-03 PDC		A CONTRACTOR OF THE CONTRACTOR	0\\
I hereby state that within 30 days the actions desc This statement of corrective actions is made in acc the NRC.	ribed by me to the inspector ordance with the requiremen	will be taken to correct the	e violations identified ether response will be	in the items checked above submitted unless required by
3 4 Dindanear	11 7.90	Jalana Ville	SNAC INSPECTOR	11 7.70