

04008698080S

SEP 22 1982

- 1 -

DISTRIBUTION
Docket File 40-8771

- ~~PDR~~
- WMUR r/f
- WMUR w/f
- NMSS r/f
- NRC Region IV
- TEFleming
- JJLinsahan
- HJPettengill
- DEMartin
- RDSmith
- REBrowning
- JBMartin
- BFisher

WMUR:TEF
Docket No. 40-8698

MEMORANDUM FOR: Docket File No. 40-8698

FROM: Thomas E. Fleming, Project Manager
New Facilities Section
Uranium Recovery Licensing Branch
Division of Waste Management

SUBJECT: PREOPERATIONAL SAFETY INSPECTION CONDUCTED UNDER
SOURCE MATERIAL LICENSE SUA-1371 FOR THE SHOOTARING CANYON
URANIUM MILL

A preoperational inspection of the facilities at the Plateau Resource Limited (PRL) Shootaring Canyon Mill was conducted on April 6-7, 1982 by a NRC Region IV inspector. The inspection was an examination of the activities conducted under the license as they relate to radiation safety and compliance with the Commission's rules and regulations, and the conditions of the license. The inspection consisted of selective examination of procedures and representative records, interviews of personnel, independent measurements, and observations by the inspector. As a result of the inspection, no violations of NRC requirements or other problems were found. Therefore, no licensing action is necessary regarding the April 6-7, 1981 inspection.

ORIGINAL SIGNED BY

Thomas E. Fleming, Project Manager
New Facilities Section
Uranium Recovery Licensing Branch
Division of Waste Management

Approved By: ORIGINAL SIGNED BY
Dan E. Martin, Section Leader
New Facilities Section
Uranium Recovery Licensing Branch
Division of Waste Management

Case Closed: 04008698080S
40-8698/TEF/82/09/07/0

20491

OFC	: WMUR	: WMUR	:	:	:	:	:
NAME	: TFleming:ag	: DEMartin	:	:	:	:	:
DATE	: 82/09/07	: 82/09/21	:	:	:	:	: