| NRC Form 591 | | U.S. NUCLEAR RE | GULATORY COMMISSION |
|---|---|--|---|
| (MR 81) 10 CFR 2.201 | SAFETY IN | | |
| 1 LICENSEE Shenango I 200 Merille Pttshugh | Road PA 15 205 14 LICENSE + JMBER(S) | REGIONAL OFFICE US NKC Region 1 475 allendale R King of Councilable R King of Councilable R | 1 12110 |
| 3. DOCKET NUMBERIS) 7 030 - 19345 | 4 LICENSE . JMBER(S) 37-20505 | · · · | |
| Regulatory Commissions (NRC) rules and and representative records, interviews, wit 1. Within the scope of this inspection, 2. The inspector also verified the step those actions at this time. 3. During this inspection certain of yo | regulations and the conditions of your h personnel, and observations by the in no violations were observed. | cordance with 10 CFR 19.11. | examinations of procedures ition are as follows: |
| of a | of redioactive material. 10 CFR 20.20 | . 10 CFR 20. 3(f)(1), or (f)(2). | were not properly |
| D. Records of | | License Condition Number | ere not properly maintained. |
| [1] M. A. MARTIN, M. | or | | were not made in accordance |
| 901 REG 37- | 2050308 901115 1 LIC30 20505-01 PDC | | |
| DESIGN/ | ATED ORIGINAL | RETURN ORIGINAL TO | 1E:07 |
| | te in accordance with the requirements | III be taken to correct the violations identifie of 10 CFR 2.201. No further response will 1 Ale Ale Ale Ale Ale Ale Ale Ale Ale Ale | e submitted unless required by |