



Carolina Power & Light Company

NOV 27 1990

SERIAL: NLS-90-244

United States Nuclear Regulatory Commission
ATTENTION: Document Control Desk
Washington, DC 20555

BRUNSWICK STEAM ELECTRIC PLANT, UNIT NO. 1
DOCKET NOS. 50-325 / LICENSE NOS. DPR-71
RESPONSE TO IE BULLETIN 80-13
EXAMINATION OF CORF SPRAY SYSTEM SPARGERS

Gentlemen:

IE Bulletin 80-13 requires that examinations of the core spray spargers and in-vessel core spray piping be made during each refueling outage. The results of these inspections are to be submitted to the NRC within 30 days of completing the examination.

In accordance with IE Bulletin 80-13, a visual inspection (Periodic Test 90.1) of the core spray spargers and in-vessel core spray piping of the Brunswick Steam Electric Plant, Unit 1, was completed on October 29, 1990. No cracks were found.

Please refer any questions regarding this submittal to Mr. M. R. Oates at (919) 546-6003.

Yours very truly,

L. Y. Loflin
Manager
Nuclear Licensing Section

DBB/cwh (899BNP)

cc: Mr. S. D. Ebnetter
Mr. N. B. Le
Mr. R. L. Prevatte

3

TE 11
/10

411 Fayetteville Street • P. O. Box 1551 • Raleigh, N. C. 27602

9012050329 901127
FDR ADDCK 05000325
FDC