

Amersham Corporation
40 North Avenue
Burlington, Massachusetts 01803
Telephone (617) 272-2000

71-9128

December 6, 1990

Mr. Charles E. MacDonald, Chief
Transportation Branch
Division of Safeguards and Transportation, NMSS
U.S. Nuclear Regulatory Commission
OWFN, 4E4
Washington, D.C. 20555


RE: Docket No. 71-9128

Dear Mr. MacDonald:

In response to your October 10, 1990 request for supplemental information, please find a revision to page 33 of the original renewal submission. This deletes the recommendation for a three month inspection and maintenance and replaces that with a statement requiring its performance at a three month frequency.

I hope this addresses all remaining questions on this submittal. Should you require additional information or clarifications, please feel free to contact me at (617) 272-2000, ext. 230.

Sincerely,



Lori Podolak
Radiation Safety Specialist

Enclosure

1/10/11

Maintenance

In accordance with 10 CFR 34.28, the C-8 Source Changer must be inspected and maintained as described in Section 8.2 of this manual at intervals not to exceed three months.