NOV 3 0 1990

Docket No. 030-20300

License No. 20-12836-01

DCS

Amersham Corporation ATTN: William McDaniel *Corporate Manufacturing Manager 40 North Avenue Burlington, Massachusetts 01803

Gentlemen:

Subject: Routine Inspection No. 030-20300/90-01

On September 13, 1990, Messrs. Thomas K. Thompson and John White of this office conducted a routine safety inspection at Amersham Corporation of activities authorized by the above listed NRC license. The inspection was an examination of your licensed activities as they relate to radiation safety and to compliance with the Commission's regulations and the license conditions. The inspection consisted of observations by the inspector, interviews with personnel, and a selective examination of representative records. The findings of the inspection were discussed with yourself and Cathleen Roughan at the conclusion of the inspection.

Within the scope of this inspection, no violations were identified.

In accordance with Section 2.790 of the NRC's "Rules of Practice", Part 2, Title 10, Code of Federal Regulations, a copy of this letter will be placed in the Public Document Room. No reply to this letter is required.

Your cooperation with us is appreciated.

stacerely,

1E.07 1

John R. White, Chief Nuclear Materials Safety Section C Division of Radiation Safety and Safeguards

Enclosure: NRC Region I Inspection Report Number 030-20300/90-01


cc w/encl: Public Document Room (PDR) Nuclear Safety Information Center (NSIC) Commonwealth of Massachusetts

> RETURN ORIGINAL TO REGION I

Amersham Corporation

٠

bcc w/enci: Region I Docket Room (w/concurrences) Management Assistant, DRMA



IR AMERSHAM - 0002.0.0 11/15/90