

DCD/DCB

NOV 26 1990

McDonnell Douglas Corporation
ATTN: Michael J. Dwyer
Director, Occupational Safety,
Health and Environment
Mailcode 0012491
P. O. Box 516
St. Louis, MO 63166-0516

License No. 24-02261-03
Docket No. 030-05081

Gentlemen:

This refers to the routine safety inspection conducted by Ms. E. R. Matson of this office on November 7, 1990 of activities authorized by NRC Byproduct Material License No. 24-02261-03 and to the discussion of our findings with you and Mrs. D. Hillman at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Roy J. Caniano, Chief
Nuclear Materials Safety
Section 2

Enclosure:
Inspection Report
No. 030-05081/90001(DRSS)

cc w/enclosure
DCD/DCB (RIDS)

RIII
Matson/sd
11/20/90

RIII
Caniano
11/20/90

9012100363 901126
REGS LIC30
24-02261-03 FDC

IE07