

OCT 5 1982

APPENDIX A

NOTICE OF VIOLATION

Harrel, Incorporated

East Norwalk, Connecticut 06855

Docket Nos. 30-11491

30-11492

License Nos. 06-16699-01

06-166999-02G

As a result of the inspection conducted on May 18, 1982, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C), the following violations were identified:

- A. Condition 8.A of License No. 06-16699-01 limits the amount of americium-241 that may be possessed at any one time to a total of 1.5 curies.

Contrary to the above, during the second quarter of 1978, Harrel, Inc., possessed at least 2.7 curies of americium-241, an amount in excess of this limit.

This is a Severity Level IV violation. (Supplement VI)

- B. Condition 9.A of License No. 06-16699-01 limits manufacture and installation of industrial gauges containing Americium-241 to Harrel, Incorporated, Models TG-601, TG-602, TG-603 and TG-604 nuclear thickness gauges. Condition 3 of License No. 06-16699-02G limits distribution to persons generally licensed pursuant to 10 CFR 31.5 of Harrel, Incorporated, Models TG-601, TG-602, TG-603, and TG-604 nuclear thickness gauges.

Contrary to the above, since January 1978, Harrel, Incorporated has manufactured and installed and transferred to persons generally licensed pursuant to 10 CFR 31.5 nuclear thickness gauges, models TG-601B, TG-601C, TG-601D, TG-603B, TG-603C, TG-603D, TG-603E, and TG-606, devices not authorized by these licenses.

This is a Severity Level IV violation. (Supplement VI)

Pursuant to the provisions of 10 CFR 2.201, Harrel Inc., is hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

OFFICIAL RECORD COPY