

CONTROL BLOCK: [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] [ ] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[0] [1] [P] [A] [S] [E] [S] [1] [2] [0] [0] [0] [0] [0] [0] [0] [0] [0] [0] [0] [3] [4] [1] [1] [1] [1] [4] [ ] [ ] [5]  
7 8 9 14 15 25 26 30 37 CAT 38  
LICENSEE CODE LICENSE NUMBER LICENSE TYPE

CON'T  
[0] [1] REPORT SOURCE [L] [6] [0] [5] [0] [0] [0] [3] [8] [7] [7] [0] [9] [1] [0] [8] [2] [8] [1] [0] [0] [8] [8] [2] [9]  
7 8 26 31 36 38 43 45 49 50 54 55 59 60 64 65 69 70 74 75 79 80  
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

[0] [2] During startup testing, while performing a surveillance of the Rod Worth  
[0] [3] Minimizer, the selection error indicating light did not operate properly. This  
[0] [4] resulted in entry into an action statement, which is reportable per 6.9.1.9.b.  
[0] [5] The action statement was met, therefore, no adverse consequences existed.  
[0] [6]  
[0] [7]  
[0] [8]

[0] [9] SYSTEM CODE [1] [F] (11) CAUSE CODE [E] (12) CAUSE SUBCODE [A] (13) COMPONENT CODE [X] [X] [X] [X] [X] [X] (14) COMP. SUBCODE [Z] (15) VALVE SUBCODE [Z] (16)  
7 8 9 10 11 12 13 18 19 20  
LER/RO REPORT NUMBER (17) [8] [2] (21) SEQUENTIAL REPORT NO. [0] [2] [1] (24) OCCURRENCE CODE [ ] (27) REPORT TYPE [L] (30) REVISION NO. [0] (32)  
ACTION TAKEN [3] (18) FUTURE ACTION [Z] (19) EFFECT ON PLANT [Z] (20) SHUTDOWN METHOD [Z] (21) HOURS [0] [0] [0] [0] (22) ATTACHMENT SUBMITTED [N] (23) NPED-4 FORM SUB. [N] (24) PRIME COMP. SUPPLIER [Z] (25) COMPONENT MANUFACTURER [Z] [9] [9] [9] (26)  
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

[1] [0] The light failed to function as a result of one 28V conductor being pulled  
[1] [1] loose from the light assembly. Stress in the cable may have been the root cause.  
[1] [2] The conductor was reterminated, and the surveillance passed.  
[1] [3]  
[1] [4]

[1] [5] FACILITY STATUS [B] (28) % POWER [0] [0] [0] (29) OTHER STATUS n/a (30) METHOD OF DISCOVERY [B] (31) DISCOVERY DESCRIPTION surveillance testing (32)  
7 8 9 10 12 13 44 45 46 80

[1] [6] ACTIVITY CONTENT RELEASED OF RELEASE [Z] (33) AMOUNT OF ACTIVITY n/a (35) LOCATION OF RELEASE n/a (36)  
7 8 9 10 11 44 45 80

[1] [7] PERSONNEL EXPOSURES NUMBER [0] [0] [0] (37) TYPE [Z] (38) DESCRIPTION n/a (39)  
7 8 9 11 12 13 80

[1] [8] PERSONNEL INJURIES NUMBER [0] [0] [0] (40) DESCRIPTION n/a (41)  
7 8 9 11 12 80

[1] [9] LOSS OF OR DAMAGE TO FACILITY TYPE [Z] (42) DESCRIPTION n/a (43)  
7 8 9 10 80

[2] [0] PUBLICITY ISSUED DESCRIPTION [N] (44) 8210210446 821008 PDR ADOCK 05000387 S PDR NRC USE ONLY  
7 8 9 10 88 89 90