

Docket 40-8027
License SUB-1010

APR 22 1994

MEMORANDUM FOR: Joseph Yardumian, Acting Chief
Operations Branch
Division of Fuel Cycle Safety
and Safeguards, NMSS

FROM: Robert C. Pierson, Chief
Licensing Branch
Division of Fuel Cycle Safety
and Safeguards, NMSS

SUBJECT: TECHNICAL ASSISTANCE REQUEST

The FCSS Licensing Branch requests technical assistance in reviewing the following project:

Project: Lessons Learned from the Sequoyah Fuels Corporation nitric oxide release on November 17, 1992.

Casework/PPSAS/TAC Nos: 40-8027/3231/L30654

Please reference the above TAC No. in future correspondence related to this request.

Background: On November 17, 1992, Sequoyah Fuels Corporation had a release of nitric oxide from its process area. As a result of this event, an augmented inspection team (AIT) was sent to the site to investigate the cause of the release.

Requested Action: Review AIT Report No. 40-8027/92-30 to identify generic safety and emergency preparedness and response issues that can be related to other fuel cycle facilities. This review should be completed, with a written response sent to the Project Manager on or before May 13, 1994.

Contact: Project Manager (PM) - Elaine Keegan, telephone 504-3354

Please notify the PM of your contact.

ORIGINAL SIGNED BY
Robert C. Pierson

Robert C. Pierson, Chief
Licensing Branch
Division of Fuel Cycle Safety
and Safeguards, NMSS

Enclosure:
Augmented Inspection Team
Report No. 40-8027/92-30

NRC FILE CENTER COPY

Distribution: w/o encl.

Docket 40-8027 PDR/LPDR NRC File Center FCLB R/F
NMSS R/F FCSS R/F FCLSI R/F

*see previous concurrence.

[G:\SFCFCSS.TAR]

OFC	FCLB	FCLB	E	FCLB	C	FCLB	C
NAME	EKeegan*:cw	DAHoadley		CMeigh		RPierson	
DATE	04/22/94	04/22/94		04/22/94		04/22/94	

260716 = COVER

E = COVER & ENCLOSURE

N = NO COPY

9404260374 940422
PDR ADDCK 04008027
C PDR

NFC3 1/0

Docket 40-8027
License SUB-1010

MEMORANDUM FOR: Joseph Yardumian, Acting Chief
Operations Branch
Division of Fuel Cycle Safety
and Safeguards, NMSS

FROM: Robert C. Pierson, Chief
Licensing Branch
Division of Fuel Cycle Safety
and Safeguards, NMSS

SUBJECT: TECHNICAL ASSISTANCE REQUEST

The FCSS Licensing Branch requests technical assistance in reviewing the following project:

Project: Lessons Learned from the Sequoyah Fuels Corporation nitric oxide release on November 17, 1992.

Casework/PPSAS/TAC Nos: 40-8027/3231/L30654

Please reference the above TAC No. in future correspondence related to this request.

Background: On November 17, 1992, Sequoyah Fuels Corporation had a release of nitric oxide from its process area. As a result of this event, an augmented inspection team (AIT) was sent to the site to investigate the cause of the release.

Requested Action: Review AIT Report No. 40-8027/92-30 to identify generic safety and emergency preparedness and response issues that can be related to other fuel cycle facilities. This review should be completed, with a written response sent to the Project Manager on or before May 13, 1994.

Contact: Project Manager (PM) - Elaine Keegan, telephone 504-3354

Please notify PM of your contact and schedule for the above project.

Robert C. Pierson, Chief
Licensing Branch
Division of Fuel Cycle Safety
and Safeguards, NMSS

Enclosure:
Augmented Inspection Team
Report No. 40-8027/92-30

Distribution: w/o encl.

Docket 40-8027 PDR/LPDR NRC File Center FCLB R/F
NMSS R/F FCSS R/F FCLSI R/F

[G:\SFCFCSS.TAR]

OFC	FCLB	E	FCLB	FCLB	FCLB
NAME	EKeegan: cw		DAHoadley	CEmeigh	RPierson
DATE	04/22/94		04/ /94	04/ /94	04/ /94

C = COVER

E = COVER & ENCLOSURE

N = NO COPY