

NOTICE OF VIOLATION

Commonwealth Edison Company
Braidwood Station, Units 1 and 2
Braceville, Illinois

Docket Nos. 50-456; 50-457
License Nos. NPF-72; NPF-77

As a result of an inspection conducted from February 23 through April 1, 1994, and in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (1993), the following violation was identified:

Technical Specification 6.8.1 requires that written procedures shall be established, implemented, and maintained covering activities referenced in Appendix A, Regulatory Guide 1.33, Revision 2, February 1978, which includes the fire protection program.

Braidwood Administrative Procedure 1100-11, "Fire Prevention for use of Lumber and Other Combustibles", Revision 2, requires combustibles transported into plant areas which will be left unattended shall have prior authorization by the Station Fire Marshal/designee by completing a Transient Fire Load Permit. After reviewing the loading to be added to each indicated fire zone, the Fire Marshal/designee shall approve the permit and issue a Permit Number with the required number of Approved Transient Fire Load Tags.

Contrary to the above, on March 8, 1994, numerous examples of combustible materials were identified being left unattended in the auxiliary and turbine buildings without obtaining a transient combustible authorization. The fire loading for areas with transient combustibles had not been reviewed and Transient Fire Load Permits had not been issued.

This is a Severity Level IV violation (Supplement I) (50-456/94007-02(DRP); 50-457/94007-02(DRP)).

The inspection showed that steps had been taken to correct the identified violation and to prevent recurrence. Consequently, no reply to the violation is required and we have no further questions regarding this matter.

Dated at Lisle, Illinois
this 14th day of April 1994