		- Low Contraction
anne ga an barran an a		PUBLIC
NRC FORM 591 PART 1 (7-91)	CAPPER .	U.S. NUCLEAR REGULATORY COMMIS
10 CFR 2.201	SAFETY	INSPECTION
a and the second second second second second second		Page 1 of
I. LICENSEE		2. REGIONAL OFFICE
Good Samaritan Hospita 520 S. 7th ST. Vincennes, In. 47591		REGION III U S NUCLEAR REGULATORY COMMISSION 799 ROOSEVELT ROAD GLEN ELLYN IL 60137
030-10241	4. LICENSE NUMBER(5 13-01787-04	5. DATE OF INSPECTION Feb. 25, 1994
questions on those actions at t	steps you have taken to correct this time. of your activities, as described	ct the violations identified during the last inspection. We have no further below or attached, were in violation of NRC requirements. This form is a
		was not properly posted to
indicate the presence of	a	10 CFR 20.203(b),(c),(d),(e) or 34.
Β.		of sealed sources were not
performed at the proper	frequencies. 10 CFR	or License Condition Number
C. Records of	and the second	were not properly maintained.
10 CFR	or License Condition N	lumber
D. Documents were not pro	operly posted or otherwise mad	te available. 10 CFR 19.11.
E. Reports or notification of		were not made in accordance with
		lumber
	with the second	
Fri and the second seco		
	225	
9404270059 9403		
9404270059 9402 PDR ADOCK 0301 C	10241 PDR	
9404270059 9402 PDR ADOCK 0303 C	10241	
9404270059 940: PDR ADOCK 030: C	10241	
PDR ADOCK 0301 C	tions described by me to the	Inspector will be taken to correct the violations identified in the items check I the requirements of 10 CFR 2.201. No further response will be submitted
PDR ADOCK 0301 C	tions described by me to the	Inspector will be taken to correct the violations identified in the items check I the requirements of 10 CFR 2.201. No further response will be submitted SIGNATURE NRC INSPECTOR DATE