


YANKEE ATOMIC ELECTRIC COMPANY

1671 Worcester Road, Framingham, Massachusetts 01701

2.C.2.11
FYR 82-94

September 27, 1982

United States Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region I
631 Park Avenue
King of Prussia, PA 19406

Attention: Mr. Ronald C. Haynes
Regional Administration

References: (a) License No. DPR-3 (Docket No. 50-29)
(b) I&E Letter to YAEC, dated September 1, 1982,
Inspection 50-29/82-08

Subject: Response to Inspection

Dear Sir:

Reference is made to I&E Inspection No. 50-29/82-08 conducted by your Mr. S. J. Collins on July 9-30, 1982, at the Yankee Atomic Electric Company Nuclear Power Station in Rowe, Massachusetts. The report made subsequent to that inspection identified one item that apparently was not conducted in full compliance with NRC requirements. In accordance with NRC's "Rules and Practices", Part 2, Title 10 Code of Federal Regulations, we hereby submit in Attachment "A" our response to that item. This information in Attachment "A" is considered proprietary and should be withheld from public disclosure pursuant to 10CFR2.790.

We trust this information is satisfactory; however, should you have any further questions, please feel free to contact us.

Very truly yours,

YANKEE ATOMIC ELECTRIC COMPANY

L. H. Heider
Vice President

/dd

ATTACHMENT "A"

In response to I & E Inspection Report 50-29/82-08, Appendix A, Notice of Violation, Yankee Atomic Electric Company submits the following information.

THIS PAGE, CONTAINING SAFEGUARDS INFORMATION,
NOT FOR PUBLIC DISCLOSURE, IS INTENTIONALLY
LEFT BLANK