

APPENDIX A
NOTICE OF VIOLATION

Tennessee Valley Authority
Belleville

Docket Nos. 50-438
License Nos. CPPR-122

As a result of the inspection conducted on June 7-10, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified.

10 CFR 50, Appendix B, Criterion V as implemented by the FSAR Section 17.1A.5 requires that activities affecting quality be accomplished in accordance with procedures. QC Procedure 1.3 paragraph 7.1e requires "Space heaters enclosed in electrical items shall be energized."

Contrary to the above, on June 8, 1982, the space heaters located in the generator section of Emergency Diesel Generator, IRT-EBM-001G-B were not energized.

This is a Severity Level V Violation (Supplement II).

Date: JUN 28 1982