Attachement to AECM-82/485 Page 1 of 1

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 M S G G S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 6 57 CAT 58
CON'T 0 1 REPORT L 6 0 5 0 0 4 1 6 7 0 9 1 8 8 2 8 1 0 1 8 8 2 9
During cold shutdown, as required by a planned maintenance activity, nine fire barrier
[0] penetrations were broken. The penetrations are located in the Auxiliary Building and
[0] 4 Control Building. This resulted in a LCO in accordance with T.S.3.7.7. This event
[0 [5] [is being reported pursuant to T.S.6.9.1.13.b. There was no effect on the health and
0 6 safety of the public and no threat to plant safety.
0 7
7 8 9
SYSTEM CODE CAUSE CAUSE SUBCODE SUBCOD
LER/RO EVENT YEAR SEQUENTIAL REPORT NO. 17 REPORT 8 2
routed. Operations was notified prior to the fire barrier penetrations leing broken.
An hourly fire watch was established in accordance with T.S.3.7.7. The work was
[1] [completed on 9/21/82. After the work was completed, the fire barriers were resealed
and the LCO was lifted. This is being submitted as a final report.
FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 NA A 31 Conduit installation
1 1 1 1 1 1 1 1 1 1
7 B 9 10 11 44 45 80 PERCONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
1 7 0 0 0 37 Z 38 NA 7 8 9 11 12 13 PERSONNEL INJURIES 80
NUMBER DESCRIPTION 41
7 8 9 11 12 LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION 43
1 9 Z 42 NA
PUBLICITY 6: 8210220282 821018 NRC USE ONLY
SSUED DESCRIPTION (45) PDR ADOCK 05000416 PDR