



MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

JAMES P. McGAUGHY, JR.
ASSISTANT VICE PRESIDENT

Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Region II
101 Marietta St., N.W., Suite 3100
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station
Unit 1
Docket No. 50-416
License No. NPF-13
File 0260/L-835.0
Containment Ventilation
Monitoring System Effluent
Flowrate Monitor -
Improper Indication of Flow
Reference: LER 82-081/03 L-0
AECM-82/484

82 OCT 19
AD: 05
USNRC REGION II
ATLANTA, GEORGIA

During the performance of the Containment Cooling Pre-Operational Test, the flow sensor for the Containment Ventilation System Effluent Flowrate failed to give proper indication. T.S.3.3.7.12 requires the flow monitor to be fully operable at all times. Attached is LER-82-081/03 L-0.

Yours truly,

JPM:sap
Attachment

- cc: Mr. N. L. Stampley (w/a)
- Mr. R. B. McGehee (w/o)
- Mr. T. B. Conner (w/o)
- Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a)
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Document Control Desk (w/a)
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

B210220284 B21018
PDR ADOCK 05000416
S PDR

OFFICIAL COPY
LE 22