

NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20656

SAFETY EVALUATION BY THE OFFICE OF NUCLEAR REACTOR REGULATION RELATED TO AMENDMENT NOS. 142 AND 125 TO FACILITY OPERATING LICENSE NOS. NPF-4 AND NºF-7 VIRGINIA ELECTRIC AND POWER COMPAN. OLD DOMINION ELECTRIC CCUPERATIVE NORTH ANNA POWER STATION, UNITS NO. 1 AND NO. 2 DOCKET NOS. 50-338 AND 50-339

1.0 INTRODUCTION

By letter dated August 22, 1990, the Virginia Electric and Power Company (the licensee) proposed a change to the Technical Specifications (TS) for the North Anna Power Station, Units No. 1 and No. 2 (NA-1&2). Specifically, the change would provide for and document exceptions to ANS-3.1 (12/79 Draft) in the NA-1&2 station staff organization and the qualification requirements regarding the position of Operations Manager as described in the standard. Also, a change would be made to TS 6.2 and 6.4 to revise the title of the "Nuclear Safety Engineering" group to "Station Nuclear Safety."

2.0 DISCUSSION

The proposed change to TS 6.3, "Facility Staff Qualifications," adds specific exceptions to the qualification requirements of ANS-3.1 (12/79 Draft) for the Superintendent Operations and the Supervisor Shift Operations.

ANS-3.1 (12/79 Draft), which is cited in TS 6.3 for establishing the qualification requirements of the plant's staff, requires that the individual fulfilling the function of the "Operations Manager" holds a current Senior Reactor Operator's (SRO) license. In the past, the licensee has determined that the Superintendent Operations is the equivalent position in the licensee's NA-1&2 organization and therefore, the position has been filled by persons holding SRO licenses.

This requirement makes it difficult for the Superintendent Operations to perform certain management functions. Specifically, the ability to monitor the quality of operating shift qualification and requalification programs is substantially impaired. The superintendent is not free to fully examine the training programs in progress, simply because he is also a trainee and is thus restricted from obtaining certain information. In addition, a substantial part of the Superintendent Operations' time is consumed in maintaining the SRO license in an active status, which requires 60 days of requalification time each year.