



SAFEGUARDS INFORMATION

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
101 MARIETTA STREET, N.W., SUITE 2900
ATLANTA, GEORGIA 30323-0199

Report Nos. 50-280/94-07 and 50-281/94-07

Licensee: Virginia Electric and Power Company
Glen Allen, VA 23060

Docket Nos. 50-280 and 50-281

License Nos. DPR-32 and DPR-37

Facility Name: Surry 1 and 2

Inspection Conducted: February 28 - March 4, 1994

Inspector: W. W. Stanberry, Safeguards Inspector

3/28/94
Date Signed

Approved by: D. McGuire
D. McGuire, Chief
Safeguards Section
Nuclear Materials Safety and Safeguards Branch
Division of Radiation Safety and Safeguards

3/28/94
Date Signed

SUMMARY

Scope:

This routine, announced inspection was conducted in the area of Physical Security Program of Power Reactors. Specific areas evaluated were: Security Program Plans; Audits; Protected Area Physical Barriers; Alarm Stations; Testing, Maintenance and Compensatory Measures; and Security Training and Qualification.

Results:

In the areas inspected, violations or deviations were not identified. Licensee's strengths observed during this inspection were as follows:

- Cooperation between Security and Audit functions during an internal audit.
- Performance of duty of the Instrument and Calibration, and Security personnel.
- Protected Area physical barrier penetration resistance capability.
- Contingency hardware provided response force personnel.
- Computer utilization for the Security Base Testing and Management Instruction program, and the Security Tracking and Treading of Repairs and Maintenance program.

The licensee continues to protect and secure the vital resources of this site.

9404290012 940329
PDR ADOCK 05000280
G PDR

SAFEGUARDS INFORMATION

Document transmitted herewith contains sensitive unclassified information. When separated from enclosures, this document is declassified.