40-3453

0400345320€€



DDR - Return 396-55

Atlas Minerals Division of Atlas Corporation Post Office Box 1207 Moab, Utah 84532-1207 Phone (801) 259-5131



August 18, 1982

Mr. Ross A Scarano, Chief Uranium Recovery Licensing Branch Division of Waste Management Office of Nuclear Material Safety & Safeguards U.S. Nuclear Regulatory Commission Washington, D.C. 20555



RE: Source Material License SUA-917 Docket NO. 40-3453

Dear Mr. Scarano.

This correspondance transmits the second quarter, 1982 quarterly report sampling and analysis results of the environmental monitoring program as required by license conditions 42, 43 and 47 of Source Material License SUA-917. It also transmits the dose evaluations to the nearest resident based on this actual environmental monitoring data and the dose conversion factors as given in attachment A of "Compliance Determination Procedures for Environmental Radiation Protection Standards for Uranium Recovery Facilities 40 CFR 190".

The Pb²¹⁰ results from the continuous air monitoring stations for the month of June and also for the quarterly ground water samples, have not yet been received from the outside laboratory. These will be forwarded to you under separate cover as soon as we receive them.

OFFICIAL DOCKET 8210260079 820818 PDR ADDCK 04003453

Q4003453201E

If additional information or clarification is needed relative to the material herewith enclosed, please contact me at your convenience.

Since ly,

Leale Q. Edward.

Dale L. Edwards Radiation Safety Coordinator

Enclosures

CC:
Mr. Glen Brown
Director of Inspection and Enforcement
Region IV
U.S. Nuclear Regulatory Commission
611 Ryan Plaza Drive
Arlington, Texas 76011

R. E. Blubaugh W. M. Jensen (w/o encl.) M. A. Drozd (w/o encl.)

DLE/rm