

APR 14 1994

Case Western Reserve University
ATTN: Warren Malchman, Director
Occupational & Environmental
Safety
10900 Euclid Avenue
Cleveland, OH 44106

License No. 34-00738-07
Docket No. 030-07040
License No. 34-00738-09
Docket No. 030-29480
License No. 34-00738-10
Docket No. 030-30177

Dear Mr. Malchman:

This refers to the routine safety inspection conducted by Ms. T. L. Simmons of this office on March 22, 1994, of activities authorized by NRC Byproduct Material License Nos. 34-00738-07, 34-00738-09 and 34-00738-10, and to the discussion of our findings with at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Original Signed by B. J. Holt

B. J. Holt, Chief
Nuclear Materials Inspection
Section 1

bcc: PUBLIC

RIII
Simmons/bt
04/17/94

RIII
Holt
4/13/94

9404290113 940414
REG3 LIC30
34-00738-07 PDR

1/0