



**Commonwealth Edison**  
Zion Generating Station  
Shiloh Blvd. & Lake Michigan  
Zion, Illinois 60099  
Telephone 312/746-2084

October 19, 1982

Mr. James G. Keppler  
Regional Director  
Directorate of Regulatory Operations  
Region III  
U.S. Nuclear Regulatory Commission  
Glen Ellyn, Illinois 60137

Reference: Zion Generating Station  
Docket No. 50-304/DPR-48  
Technical Specification, Section 6.6.2.a.2

Dear Mr. Keppler:

Enclosed please find Reportable Occurrence Report No. 50-304/82-24 for Zion Generating Station. It was reported to the resident inspector, Joe Waters on 10/5/82 and by telegram/mailgram to Region III, Directorate of Regulatory Operations on 10/5/82.

This report is submitted to you in accordance with the requirements of the Technical Specifications, Section 6.6.2.a.2 which states the operation of the unit or affected systems when any parameters or operation subject to a limiting condition is less conservative than the least conservative aspect of the limiting condition for operation established in the Technical Specifications requires a 14 day written report.

Very truly yours,

K. L. Graesser  
Superintendent  
Zion Station

KLK/WDT/ar

Enclosure: Reportable Occurrence Report No. 50-304/82-24

8210260219 821019  
PDR ADOCK 05000304  
S PDR

OCT 20 1982

IE22