

APPENDIX A

NOTICE OF VIOLATION

Genzyme Corporation  
Boston, Massachusetts 02111

Docket No. 030-21242  
License No. 20-20834-01

As a result of the inspection conducted on September 12, and 13, 1990, and in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (Enforcement Policy) (1990), the following violation was identified:

10 CFR 20.305 requires that no licensee shall treat licensed material by incineration except for material listed under 10 CFR 20.306 or as specifically approved by the Commission pursuant to 10 CFR 20.106(b) and 20.302.

Contrary to the above, on April 12, 1990, a box containing a total of approximately 1.6 millicuries of phosphorus-32 was incinerated without specific approval pursuant to 10 CFR 20.106(b) and 20.302.

This is a Severity Level IV violation (Supplement IV).

Pursuant to the provisions of 10 CFR 2.201, Genzyme Corporation is hereby required to submit to this office within thirty days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

OFFICIAL RECORD COPY

ML DL GENZYME - 0003.0 0  
12/10/90

9012180007 901211  
REG1 LIC30  
20-20834-01 PDR

RETURN ORIGINAL TO  
REGION I

IE-07