



October 17, 1990

Nuclear Materials Safety Section A
Division of Radiation Safety and Safeguards
U.S. Nuclear Regulatory Commission
Region I
475 Allendale Road
King of Prussia, PA 19406

ATTN: Dr. Mohamed M. Shanbaky

RE: Docket No. 030-08957
License No. 37-15350-01

Dear Mr. Shanbaky:

In response to your inspection report dated October 3, 1990, we have taken the following corrective steps to rectify the violations identified in your report.

1. The dose calibrator constancy check is now carried out daily and on weekends when procedures are performed using three radioactive standards of Cs-137, Co-57 and Ba-133 besides checking the constancy of six (6) other frequently used isotope settings of Tc-99m, Ga-67, Tl-201, I-123, I-131, and In-111 with Cs-137 source in the dose calibrator well chamber.

2. All elution, preparation and injection areas are now surveyed daily including weekends.

We hope the corrective steps taken above meet with your approval. Should you need further information, please do not hesitate to contact us.

Sincerely yours,

Edward H. Kennerdell
Vice President

9012180015 901207
REG: LIC30
37-15350-01 PDR