

LICENSEE EVENT REPORT

CONTROL BLOCK / / / / / / (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

/0/1/ /V/A/N/A/S/1/ (2) /0/0/-/0/0/0/0/0/-/0/0/ (3) /4/1/1/1/1/ (4) / / / (5)

/0/1/ REPORT SOURCE /L/ (6) /0/5/0/0/0/3/3/8/ (7) /0/9/1/9/8/2/ (8) /1/0/1/3/8/2/ (9)

DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
/0/2/ / On September 19, 1982 with Unit 1 in Mode 6, the routine recalibration of press-
/0/3/ / urizer level transmitter LT-1-461 revealed the transmitter to be out of calib-
/0/4/ / ration low by 1.58 percent. Redundant instrumentation was available to provide the
/0/5/ / pressurizer high level reactor trip; therefore, the health and safety of the
/0/6/ / general public were not affected. There are no generic implications associated
/0/7/ / with this event and it is reportable pursuant to T.S. 3.3.1.1 and 6.9.1.9.a.

SYSTEM CAUSE CAUSE COMP. VALVE
CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCODE
/0/9/ /I/A/ (11) /E/ (12) /E/ (13) /I/N/S/T/R/U/ (14) /T/ (15) /Z/ (16)

(17) LER/RO REPORT NUMBER /8/2/ /-/ /0/6/5/ / / /0/3/ /L/ /-/ /0/
ACTION TAKEN FUTURE EFFECT SHUTDOWN ATTACHMENT NPRD-4 PRIME COMP. COMPONENT
ACTION ON PLANT METHOD HOURS SUBMITTED FORM SUB. SUPPLIER MANUFACTURER
/C/ (18) /Z/ (19) /Z/ (20) /Z/ (21) /C/0/0/0/ (22) /N/ (23) /N/ (24) /N/ (25) /R/3/6/9/ (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

/1/0/ / The out of calibration condition was caused by instrument drift. The transmitter/
/1/1/ / was replaced by a different model as part of Design Change 81-08A. The new
/1/2/ / transmitter was calibrated and the instrument loop was returned to operable
/1/3/ / status.

/1/4/ /
FACILITY STATUS %POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)
/1/5/ /H/ (28) /0/0/0/ (29) / NA / /B/ (31) / Periodic Surveillance /

ACTIVITY CONTENT AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)
/1/6/ /Z/ (33) /Z/ (34) / NA / / NA /

PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
/1/7/ /0/0/0/ (37) /Z/ (38) / NA /

PERSONNEL INJURIES NUMBER DESCRIPTION (41)
/1/8/ /0/0/0/ (40) / NA /

LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION
/1/9/ /Z/ (42) / NA /

PUBLICITY ISSUED DESCRIPTION (45) NRC USE ONLY
/2/0/ /N/ (44) / NA / / / / / / / / / / / / / /

NAME OF PREPARER W. R. CARTWRIGHT PHONE (703) 894-5151