

December 13, 1990

Docket No. 50-029

Mr. George Papanic, Jr.
Senior Project Engineer - Licensing
Yankee Atomic Electric Company
580 Main Street
Bolton, Massachusetts 01740-1398

Dear Mr. Papanic:

SUBJECT: UNIMPLEMENTED GENERIC SAFETY ISSUES AT YANKEE ROWE

On April 25, 1990 the staff issued Generic Letter 90-04 which requested information concerning the implementation status of certain generic safety issues (GSIs) at your facility. Based on your response to this Generic Letter, dated June 27, 1990, our own records and discussions with your staff, we have updated our database on GSI implementation status. The results of this effort were presented to the Commission at a meeting on October 25, 1990.

The enclosure to this letter summarizes the staff's understanding of the current status of those GSIs which remain unimplemented at Yankee Rowe. We appreciate the assistance you provided in responding to Generic Letter 90-04 and we encourage your timely completion of those GSIs listed in the enclosure.

Please contact me if you have any questions or comments about the enclosed information.

Sincerely,

Original signed by
Patrick M. Sears, Project Manager
Project Directorate I-3
Division of Reactor Projects I/II
Office of Nuclear Reactor Regulation

Enclosure:
As stated

cc w/enclosure:
See next page

LA: PDI-3
MKusharook
12/16/90

PMS
PM: PDI-3
PMSears:mes
12/16/90

SICB
~~BT & R~~ Newberry
12/12/90

EW
D: PDI-3
RHWesman
12/13/90

OFFICIAL RECORD COPY
Document Name: YR GSI MEMO

170011

9012190195 901213
PDR ADDCK 05000029
P PDR

DF01
DF03

Mr. George Papanic, Jr.

Yankee Rowe

cc:

Dr. Andrew C. Kadak, President
and Chief Executive Officer
Yankee Atomic Electric Company
580 Main Street
Bolton, Massachusetts 01740-1398

Mr. Jay K. Thayer
Vice President And Manager
of Operations
Yankee Atomic Electric Company
580 Main Street
Bolton, Massachusetts 01740-1398

Thomas Dignan, Esquire
Ropes and Gray
225 Franklin Street
Boston, Massachusetts 02110

Mr. N. N. St. Laurent
Plant Superintendent
Yankee Atomic Electric Company
Star Route
Rowe, Massachusetts 01367

Resident Inspector
Yankee Nuclear Power Station
U.S. Nuclear Regulatory Commission
Post Office Box 28
Monroe Bridge, Massachusetts 01350

Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, Pennsylvania 19406

Robert M. Hallisey, Director
Radiation Control Program
Massachusetts Department of Public Health
150 Tremont Street, 7th Floor
Boston, Massachusetts 02111

Mr. George Sterzinger
Commissioner
Vermont Department of Public Service
120 State Street, 3rd Floor
Montpelier, Vermont 05602

Ms. Jane M. Grant
Senior Engineer - License Renewal
Yankee Atomic Electric Company
580 Main Street
Bolton, Massachusetts 01740-1398

UNIMPLEMENTED GSIs AT YANKEE ROWE

<u>GSi NO.</u>	<u>TITLE</u>	<u>PROJECTED IMPLEMENTATION DATE</u>	<u>REMARKS</u>
51(L913)	Improving the Reliability of Open-Cycle Service	2/91	Generic Letter 90-04 identified that this Water Systems item was resolved with Generic Letter 89-13. Yankee responded to GL 89-13 by a letter dated January 26, 1990. The staff responded in their letter of March 2, 1990. Yankee is scheduled to provide additional information by February 1991.
67.3.3 (A017)	Improved Accident Monitoring	TBD	Generic Letter 90-04 identified that this item was resolved with Generic Letter 82-33. Yankee responded to GL 82-33 on April 19, 1983, August 30, 1983, January 19, 1984, October 22, 1985, and September 30, 1986. The staff issued a partial SER on December 9, 1986. Yankee provided additional information to resolve the one outstanding issue on October 1, 1987. The staff is drafting a letter rejecting Yankee's position. (Task No. M66496).

DISTRIBUTION:

Docket File 50-029

NRC PDR

Local PDR

PDI-3 Reading

S. Varga

E. Greenman

M. Rushbrook

P. Sears

R. Wessman

R. Scholl

D. Miller

B. Marcus - 8 H3

OGC - 15 G18

E. Jordan - MNBB 3201

ACRS (10) - P1 35

J. Johnson, Region I