Ped bes

Caylor-Nickel Hospital ATTN: Mr. William Brockman Administrator 309 South Main Street Bluffton, IN 46714

License No. 13-01629-04 Docket No. 030-00192

Gentlemen:

This refers to the routine safety inspection conducted by Ms. D. Piskura and Mr. W. Reichhold of this office on November 1, 1990 of activities authorized by NRC Byproduct Material License No. 13-01629-04 and to the telephone discussion of our results with you on November 19, 1990.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice. A written response is required.

Violation 1 is a repeat item. In your response to this violation, please describe why your proposed corrective action is expected to be more successful than the corrective actions you took after our November 1989 inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, the enclosures, and your response to this letter will be placed in the NRC Public Document Room.

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely.

William H. Schultz, Chief Nuclear Materials Safety Section 1

Enclosure: Notice of Violation

cc w/enclosure: DCD/DCB (RIDS)

Reichhold/sd

RIII with Schultz 12-10-90 IE07

9012200024 901211 REG3 LIC30 13-01629-04 PD PDR