FORM 1 (3-1		591 . U.S. NUCLEAR REGULATORY COMMISSION OFFICE OF INSPECTION AND ENFORCEMENT
		INSPECTION FINDINGS AND LICENSEE ACKNOWLEDGMENT
I. LIC		
	1.1	spital at the Moderal College USARE Region I
0	4	Pall Ave bill Bark Ave A Burk
	30	100 Henry Ave 1 Ring of Aussia, 12 19406 hila Pa 19129
3. DO	CKE	T NUMBER(S) 4. LICENSE NUMBER(S) 8. DATE OF INSPECTION
4	33	0-03022 37-02562-01 9-14-82
The in Comm	ispe	tion Findings ction was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the in's rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and repre- ecords, interviews with personnel, and observations by the inspector. The findings as a result of this inspection are as follows:
	1	o items of noncompliance or unsafe conditions were found.
The	foll	owing items of noncompliance related to records, signs, and labels were found:
	A	Rooms or areas were not properly posted to indicate the presence of a RADIATION AREA. 10 CFR 20.203(b) or 34.42
		Rooms or areas were not properly posted to indicate the presence of a HIGH RADIATION AREA.
		10 CFR 20.203(c) (1) or 34.42
	C.	Rooms or areas were not properly posted to indicate the presence of an AIRBORNE RADIOACTIVITY AREA. 10 CFR 20.203(d)
	D	Rooms or areas were not properly posted to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(e)
	E.	Containers were not properly labeled to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(f) (1) or (f) (2)
	F.	A current copy of 10 CFR 20, a copy of the lice se, or a copy of the operating procedures was not properly posted or made available. 10 CFR 20.206(b)
	G.	Form NRC-3 was not properly posted. 10 CFR 20.206(c)
	H	Records of the radiation exposure of individuals were not properly maintained. 10 CFR 20.401(a) or 34.33(b)
	1	Records of surveys or disposals were not properly maintained. 10 CFR 20.401(b) or 34.43(d)
	J.	Records of receipt, transfer, disposal, export or inventory of licensed material were not properly maintained. 10 CFR 30.51, 40.61 or 70.51
	K	Records of leak tests were not maintained as prescribed in your license, or 10 CFR 34.25(c)
		Records of inventories were not maintained. 10 CFR 34.26
		Utilization logs were not maintained. 10 CFR 34.27
		Records of radiation survey instrument calibration were not maintained. 10 CFR 34.24
		Records of teletherapy electrical interlock tests were not maintained as prescribed in your license.
4	Ρ.	Ilreca Nale Derden
		(NRC Inspector) RC Inspector has explained and I understand the items of noncompliance listed above. The items of
		mpliance will be corrected within the next 30 days.
1	2	ept. 17, 1982 Anot A Bucker Another Alter the
1		(Date) B211010161 B20917 (I in ansee Representative - Title or Position)
RIGH	NAL	TO LICENSEE PDR ADDCK 07002304

D