FARM NRC-591 (3-77)

## U.S. NUCLEAR REGULATORY COMMISSION

Inspection - 8201

## INSPECTION FINDINGS AND LICENSEE ACKNOWLEDGMENT

Episcopal Hospital Department of Nuclear Medicine Front Street & Lehigh Avenue Philadelphia, Pennsylvania 19125			US N.R.C. Region I 631 Park Avenue King of Prussia, Pa. 19406	
3. DO	CKET NUMBER(S)	4. LICENSE NUMBER(S)	8. DATE OF INSPECTION	
30	)-3031	37-03420-01	10/20/82	
The in	nission's rules and regulations and the co	onditions of your license. The	license as they relate to radiation safety and to compliance with the inspection consisted of selective examinations of procedures and represent. The findings as a result of this inspection are as follows:	
X	No items of noncompliance or un	safe conditions were found	d.	
The	following items of noncompliance	related to records, signs, an	id labels were found:	
	A. Rooms or areas were not prope	erly posted to indicate the	presence of a RADIATION AREA. 10 CFR 20.203(b) or 34.42	
	B. Rooms or areas were not properly posted to indicate the presence of a HIGH RADIATION AREA. 10 CFR 20.203(c) (1) or 34.42			
	C. Rooms or areas were not properly posted to indicate the presence of an AIRBORNE RADIOACTIVITY AREA. 10 CFR 20.203(d)			
	D. Rooms or areas were not properly posted to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(e)			
	E. Containers were not properly labeled to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(f) (1) or (f) (2)			
	F. A current copy of 10 CFR 20, a copy of the license, or a copy of the operating procedures was not properly posted or made available. 10 CFR 20.206(b)			
	G. FormNRC-3 was not properly posted. 10 CFR 20.206(c)			
	H. Records of the radiation exposure of individuals were not properly maintained. 10 CFR 20.401(a) or 34.33(b)			
	Records of surveys or disposals	s were not properly mainta	ained. 10 CFR 20.401(b) or 34.43(d)	
	<ol> <li>Records of receipt, transfer, disposal, export or inventory of licensed material were not properly maintained. 10 CFR 30.51, 40.61 or 70.51</li> </ol>			
	K. Records of leak tests were not maintained as prescribed in your license, or 10 CFR 34.25(c)			
	L. Records of inventories were not maintained. 10 CFR 34.26			
	M. Utilization logs were not maintained. 10 CFR 34.27			
	N. Records of radiation survey instrument calibration were not maintained. 10 CFR 34.24			
	O. Records of teletherapy electrical interlock tests were not maintained as prescribed in your license.			
7. Th	P. Other 11010229 821020 6 LIC30 03420-01 PDR ne NRC Inspector has explained incompliance will be corrected w	and I understand the iter ithin the next 30 days.	ms of noncompliance listed above. The items of	
			IE07	
	(Date)		(Licensee Representative - Title or Position)	