NRC FORM 366 (12-81)	U.S. NUCLEAR REGULATORY COMMISSION LICENSEE EVENT REPORT	APPROVED BY OMB 3150-0011 EXPIRES 4-30-82
CONTROL BLOCK:	(PLEASE PRINT OR TYPE A	LL REQUIRED INFORMATION)
0 1 P A S E S 1 2 (0 0 - 0 0 0 0 0 - 0 0 3 4 L	1 1 1 1 1 3 4 57 GAT 58
CON'T 0 1 REPORT 1 6 0 5 0 7	0 0 3 8 7 7 0 9 2 2 8 2 0 CKET NUMBER 60 60 EVENT DATE 74	8 1 0 2 2 8 2 9
EVENT DESCRIPTION AND PROBAG		the D.C. seems 1
	ng, the 250 volt battery charger in	
0 3 system was placed in	service. When the output breaker w	as closed, the associ-
0 4 ated capacitor self of	destructed. The charger was removed	from service and the
0 5 action statement ente	ered. This is reportable per 6.9.1.	9.b.
0 6		
0 7		
081		
7 8 SYSTEM CAU	The state of the s	OMP. VALVE BCODE SUBCODE
E C 11 E	12 A 13 X X X X X X 14 1	Z 15 Z 16
17 REPORT 8 2 -		PORT REVISION NO.
	N N N N N N N N N N	PRIME COMP. COMPONENT OF
CAUSE DESCRIPTION AND CORRECT TO The capacitor was rep	olaced with a new style capacitor.	(The old style is no
1 1 longer in production)	and the system was returned to ser	vice. A modification
1 2 is being initiated to	incorporate a newer design to the	charging system. This
1 3 change should reduce	the potential for capacitor failure	es in the future.
1 4		
7 8 9 FACILITY STATUS 1 5 B 28 0 0 0 29		very description (32) observation
7 8 9 10 12 13 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF	44 45 46 LOCATI	ON OF RELEASE (36)
1 6 Z 3 Z 34 L	n/a n/a	80
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPT		
7 8 9 11 12 13 PERSONNEL INJURIES NUMBER DESCRIPTION (41)		80
180000	n/a	80
LOSS OF OR DAMAGE TO FACILITY 43		
PUBLICITY ISSUED DESCRIPTION 45	8211010251 821022 PDR ADOCK 05000387 S PDR	NRC USE ONLY
2 0 N (44)		68 69 80
NAME OF PREPARER	D.G. Mitchell PHON	NE: (717) 542-2181 X524