

POR

40-8698

Retuen

396

(303) 245-5460

(517) 788-1880 (801) 534-0734

General Office: 772 Horizon Drive, Grand Junction, CO 81501 Corporate Office: 212 West Michigan Avenue, Jackson, MI 49201 Registered Office: 136 South Main, Salt Lake City, UT 84101

September 17, 1982

Uranium Recovery Licensing Branch Attn: Mr. Thomas E. Fleming U. S. Nuclear Regulatory Commission Washington, D.C. 20555

RE: SHOOTARING CANYON URANIUM PROCESSING FACILITY -- EMBANKMENT AS-BUILT REPORT



Gentlemen:

The enclosed documents and photographs are submitted to fulfill the requirements of Conditions 42 and 43 of License No. SUA-1371, Docket No. 40-8698. The report entitled "Earthwork Quality Control Overview and As-Built Drawings - Construction of Stage I Tailings Impoundment and Dam -- Shootaring Canyon Uranium Project" summarizes the quality control program and findings and contains the as-built drawings of the embankment. In the "Embankment Foundation and Slush Grouting Photographs and Geologic Map" report, the photographs required by Condition 43 (b) are arranged in chronological order.

Please contact Mr. U. K. Gupta or the undersigned if you have any questions regarding these reports.

Sincerely,

Fred W. Gerdeman

Supervisor of Governmental Affairs


FredW. Derdeman

FWG:dkr

Enclosures

8211020241 820917 PDR ADDCK 04008698

OFFICIAL DOCKET COPY



20755 into only