




Public Service Company of Colorado

16805 Road 19 1/2, Platteville, Colorado 80651-9298

October 21, 1982
Fort St. Vrain
Unit No. 1
P-82469



Mr. John T. Collins, Regional Administrator
Region IV
Nuclear Regulatory Commission
611 Ryan Plaza Drive
Suite 1000
Arlington, Texas 76011

Reference: Facility Operating License
No. DPR-34

Docket No. 50-267

Dear Mr. Collins:

Enclosed please find a copy of Reportable Occurrence Report
No. 50-267/82-037, Final, submitted per the requirements of Technical
Specification AC 7.5.2(b)2.

Also, please find enclosed one copy of the Licensee Event Report for
Reportable Occurrence Report No. 50-267/82-037.

Very truly yours,

Don Warembourg
Don Warembourg
Manager, Nuclear Production

DW/clS

Enclosure

cc: Director, MIPC

FE 22