

John D. O'Toole  
Vice President

Consolidated Edison Company of New York, Inc.  
4 Irving Place, New York, NY 10003  
Telephone (212) 460-2533

September 15, 1982

Re: Indian Point Unit No. 2  
Docket No. 50-247

Mr. William G. McDonald, Director  
Office of Management Information  
and Program Control  
c/o Distribution Services Branch, DDC, ADM  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Dear Mr. McDonald:

Enclosed you will find two copies of the Monthly Operating Report relating to Indian Point Unit No. 2 for the month of August 1982.

Very truly yours,

*John D. O'Toole*

Encl.

cc: Mr. Richard DeYoung, Director (40 copies)  
Office of Inspection and Enforcement  
c/o Distribution Services Branch, DDC, ADM  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Mr. Ronald C. Haynes, Regional Administrator  
Region I  
U. S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, Pa. 19406

Mr. T. Rebelowski, Senior Resident Inspector  
U. S. Nuclear Regulatory Commission  
P. O. Box 38  
Buchanan, New York 10511

IE24