

APPENDIX A
NOTICE OF VIOLATION

The Bridge Construction Corporation
Augusta, Maine 04330

Docket No. 030-29218
License No. 18-27827-01

As a result of the inspection conducted on November 12, 1990, and in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (Enforcement Policy) (1990), the following violations were identified:

- A. License Condition 16. of NRC License No. 18-27827-01 requires that licensed material be used in accordance with statements, representations, and procedures contained in an application dated April 29, 1986.

Item 7 of this application names an individual who will be responsible for the radiation safety program, and indicates that this individual will complete the Troxler Nuclear Gauge Training Course.

Contrary to the above, as of November 12, 1990, the named individual has never been responsible for the Licensee's radiation safety program nor has he completed the required training course.

This is a Severity Level IV violation. (Supplement IV).

- B. License Condition 13.(A)(1) of NRC License No. 18-27827-01 requires that the source be tested for leakage and/or contamination at intervals not to exceed six (6) months.

Contrary to the above, as of November 12, 1990, a sealed source containing eight (8) millicuries of cesium-137 and forty (40) millicuries of americium-241 has not been tested for leakage and/or contamination since 1987, an interval greater than six (6) months.

This is a Severity Level IV violation. (Supplement IV)

- C. License Condition 15. of NRC License No. 18-27827-01 requires that a physical inventory be conducted every six (6) months to account for all sources received and possessed under the license.

Contrary to the above, as of November 12, 1990, the required physical inventories have not been conducted.

This is a Severity Level IV violation. (Supplement IV)

Pursuant to the provisions of 10 CFR 2.201, The Bridge Construction Corporation is hereby required to submit to this office within thirty days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

OFFICIAL RECORD COPY ML DL BRIDGE - 0003.0.0

9101020086 901219
REG1 LIC30
18-27827-01 PDR

RETURN ORIGINAL TO
REGION I

IE:07