NRC Form 591	The second secon	U.S. NUCLEAR REGULATORY COMMISSION
12-81) 0 CFR 2.201	SAFETY INSPECTION	POPPEB
BOWLER GREEN, OH	THEORY 799 KOUSE	1027 Runo 1027 Runo 10, IL 60137
	LICENSE NUMBER(S)	5. DATE OF INSPECTION
030-08785 S	34-15236-01	27 Alovember 1990
he inspection was an examination of the activities continguistory Commissions (NRC) rules and regulations and representative records, interviews, with personnel, a	nd the conditions of your license. The inspection and observations by the inspector. The findings as	consisted of selective examinations of procedures
2. The inspector also verified the steps you have tak those actions at this time.	en to correct the violations identified during the l	ast inspection. We have no further questions on
During this inspection certain of your activities, a THIS IS A NOTICE OF VIOLATION which is re		
Of 8		was not properly posted to indicate the presence
B. Containers located in		were not properly
frequencies 10 CFR D. Records of		if sealed sources were not performed at the proper dition Number
10 CFR	or Linense Condition Numb	
E. Documents were not properly posted or other	wise made available. 10 CFR 19.11.	were not made in accordance
with 10 CFR	or License Condition Numb	96r
DHAW AT THE END OF	THE DAY AS REQUIRED	A DE THE DAY MITTERS. BY 10058 35 70(3).
J		
K.,		
hereby state that within 30 days the actions described to his statement of correctly actions is made in accordance NRC.	ov me to the inspector will be taken to correct the re with the requirements of 10 CFR 2.201. No fur	violations identified in the item, checked above. their response will be sufmitted unless equired by
9101020227 901127 RE03 LIC30 34-15234-01 PDR	DATE	- NAC INSPECTOR DATE