



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

October 29, 1982

Regional Administrator
Region III
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Type B Containment Leakage Test Failures
RO-82-10, 11, 12, and 14

The License Event Reports for these occurrences are attached.

These events are reported in compliance with Technical Specification 6.7.B.1.c since they represent degradation of containment isolation valves.

Simon Fahn
for David Musolf
Manager - Nuclear Support Services

DMM/SAF/bd

cc: NRC Document Control Desk (1)
NRC Resident Inspector
MPCA
Attn: J W Ferman