

Appendix

NOTICE OF VIOLATION

Commonwealth Edison Company

Docket No. 50-237

Docket No. 50-249

As a result of the inspection conducted during August 10 through September 3, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified:

Technical Specification 4.12.A.1, concerning fire detection instrumentation surveillance requirements states, "Each of the fire detector instruments given by Table 3.12-1 shall be demonstrated OPERABLE at least every six months by a channel functional test." For the Main Control Room, Table 3.12-1 lists 34 fire detectors. Technical Specification 4.12.D.2., concerning Carbon Dioxide system surveillance requirements states that the Carbon Dioxide system shall be demonstrated OPERABLE at least once per 31 days by verifying that each valve, manual, power-operated, or automatic, in the flow path is in the correct position.

Contrary to the above, the licensee failed to perform the required surveillance in that:

- a. Only 32 of the 34 detectors listed by the Technical Specification for the Control Room were being tested.
- b. A manual isolation valve in the Carbon Dioxide system was not checked every 31 days.

This is a Severity Level IV violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Dated

R. L. Spessard, Director
Division of Project and
Resident Programs