YANKEE ATOMIC ELECTRIC COMPANY



2 ° 8 *

Rowe, Massachusetts 01367

October 27, 1982

Mr. R. C. Haynes, Director U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region I 631 Park Avenue King of Prussia, Pennsylvania 19406

Subject: Licensee Event Report 50-29/82-31-03L Primary Vent Stack Radioiodine Monitor Failed Surveillance

Dear Mr. Haynes:

In accordance with Technical Specifications, Section 6.9.4.b the attached Licensee Event Report is hereby submitted.

Very truly yours,

Montunt a antio

Herbert A. Autio Plant Superintendent

DAR/amt

Enclosures:

- cc: [30] Director, Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, D.C. 20555
 - [3] Director, Officer of Management Information & Program Control U.S. Nuclear Regulatory Commission Washington, D.C. 20555
 - [14] NSARC Chairman
 - [1] Manager of Operational Quality Assurance (YAEC)
 - [1] Institute of Nuclear Power Operations (INPO)

