

## SAFEGUARDS INFORMATION

## NUCLEAR REGULATORY COMMISSION REGION II

101 MARIETTA STREET, N.W. ATLANTA, GEORGIA 30323

Report No.: 50-261/90-29

Licensee: Carolina Power and Light Company

P. O. Box 1551 Raleigh, NC 27602

Docket No.: 50-261

License No.: DPR-23

Facility Name: H. B. Robinson

Inspection Conducted: December 2-7, 1990

A. Tillman, Safegurds Inspector

Date Signed

Approved by:

D. R. McGuire, Chief

Safegurds Secetion Nuclear Materials

Safety and Safeguards Branch

Division of Radiation Safety and Safeguards

SUMMARY

Scope:

This routine, unannounced inspection was conducted in the areas of Physical Security Program for Power Reactors, specifically, Management Support, Security Program Plans and Audits; Protected and Vital Area Physical Barriers; Detection and Assessment Aids; Lighting; Protected and Vital Area Access Control of Personnel, Packages and Vehicles; Alarm Stations and Communications; Compensatory Measures, and Physical Protection of Shipment of Irradiated Fuel.

Results:

In the areas inspected, violations or deviations were not identified.

Inspection results indicated that the security organization continues to function at the level of effectiveness noted in previous inspections. The program continues to be well managed and receives adequate support from senior plant management. With regard to the rail shipment of irradiated fuel from the H. B. Robinson Nuclear Plant to S. Harris Nuclear Plant, a delay of several hours in the scheduled departure time occurred as a result of equipment problems with both the licensee and CSX rail equipment. However, upon departure from the H. B. Robinson Plant, the shipment proceeded in a timely manner without incident. Adequate security and communications capability were provided.

9101040039 901227 PDR ADOCK 05000261

Descripted transmitted by swifts remain an walled surclassified internal will be described train and have the transmitted to the concentrated.