



J.E. WATSON
CITY ENGINEER

DEPARTMENT OF PUBLIC SERVICE
BUREAU OF ENGINEERING
701 MUNICIPAL BUILDING
375-2095

C. DAVID HAIGH
DEPUTY CITY ENGINEER

October 26, 1982

United States
Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Attention: Mr. D. J. Sreniawski, Chief
Materials Radiation Protection
Section 2

Gentlemen:

In response to our notice of violation dated September 29, 1982, I will address the findings of your inspection.

Item: (1) We have received a leak test kit from troxler, and submitted a test patch to them on October 19, 1982. There are enough swabs in the kit to run a test every six month (as required by license no 34-20-183-01) for a two year period.

Item: (2) We have purchased a padlock for the gauge and the source rod is now locked when not in use. The gauge is being stored in a room that is now locked and only authorized personnel have the key.

The corrective action was taken as soon as your violation notice was received, and I will take daily inspections to see that we stay in compliance with our license.

Sincerely,

Thomas H. Butler / pmc
T. H. Butler
Radiation Protection Officer

THB:pe

cc: File

8211060211 821029
NMS LIC30
34-20183-01 PDR

OCT 28 1982