

John D. O'Toole  
Vice President

Consolidated Edison Company of New York, Inc.  
4 Irving Place, New York, NY 10003  
Telephone (212) 460-2533

October 22, 1982

Re: Indian Point Unit No. 2  
Docket No. 50-247  
LER-82-042/03L-0


Mr. Ronald C. Haynes,  
Regional Administrator-Region I  
U. S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, Pa. 19406

Dear Mr. Haynes:

The attached Licensee Event Report LER-82-042/03L-0 is hereby submitted in accordance with the requirements of Technical Specification 6.9.1.7. This event is of the type described in Technical Specification 6.9.1.7.2.b.

Three copies of this letter and the attachment are enclosed as required.

Very truly yours,



attach.  
cc:

Mr. Richard DeYoung, Director (30 copies)  
Office of Inspection and Enforcement  
c/o Distribution Services Branch, DDC, ADM  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Mr. William G. McDonald, Director (3 copies)  
Office of Management Information and Program  
Control  
c/o Distribution Services Branch, DDC, ADM  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Mr. Thomas Foley, Senior Resident Inspector  
U. S. Nuclear Regulatory Commission  
P. O. Box 38  
Buchanan, New York 10511

8211060282 821022  
PDR ADDOCK 05000247  
S PDR

*IER*