Telephone (617) 872-8100 TWX 710-380-7619

YANKEE ATOMIC ELECTRIC COMPANY



1671 Worcester Road, Framingham, Massachusetts 01701

2.C.2.1 FYR 82-108

A046

November 2, 1982

United States Nuclear Regulatory Commission Washington, D. C. 20555

Attention: Mr. Dennis M. Crutchfield, Chief Operating Reactors Branch No. 5 Division of Licensing

References:	 (a) License No. DPR-3 (Docket No. 50-29) (b) USNRC Letter to YAEC, dated September 23, 1982 (c) YAEC Letter to USNRC, dated June 11, 1982 (FYR 82-56)
Subject:	Request for Additional Information: TMI Action Plant Item II.B.4.1

Dear Sir:

Reference (b) requested additional information on our Mitigating Core Damage Training Program; specifically, as it applied to (1) new personnel who would require the initial training, and (2) requirements for re-training after the initial program has been given.

In response to Reference (b), the general plant training program and procedure will be revised to include initial training and refresher training in mitigating core damage as described in Reference (c). The procedure outlines which personnel are required to receive mitigating core damage training as outlined in Item 6 of Reference (c). The procedure will also detail the training required for new personnel entering into a position in which mitigating core damage training is required.

In addition, refresher training in mitigating core damage will be provided. All personnel who were required to receive the initial training will be given refresher training. The training procedure is being revised to include a min.mum of four (4) hours of refresher training be conducted annually. The training manager will determine the content of the mitigating core damage retresher training required.

We trust this information is satisfactory; however, if you have any further questions, please contact us.

Very truly yours,

YANKEE ATOMIC ELECTRIC COMPANY

J. A. Kav

Senior Engineer - Licensing

8211090231 821102 PDR ADUCK 05000029 PDR PDR

JAK/dd