Mid Continent Nuclear Consultants

4305 Foxglove Lane Oklahoma City, OK 73120 (405) 751-6937

UIT	X	Armer an Armere	
NT .	DEC 2	1 1990	
	UCL L	I REPORT	/

December 17, 1990

Mr. A. Bill Beach, Director Division of Radiation Safety & Safeguards U. S. Nuclear Regulatory Commission Region IV 611 Ryan Drive, Ste. 1000 Arlington, Texas 76001

Re: License: 35-23137-01 Docket: 30-20298 EA: 90-003

Dear Mr. Beach:

On December 15th, I conducted the first of three quarterly audits of Petro Data's operations involving radioactive materials. My report follows:

 Records - All records were current. Survey meter calibrations and leak test (for those sources used in operations) had been performed within the past few weeks.

Copies of the regulations (10CFR Parts 19, 20 and 39 and a copy of the 0 & E Procedures manual and a copy of the license were on file.

Training records were current. One man currently working as a Logging Assistant, is to be upgraded to Logging Supervisor within the next few months.

- 2. Control Chart current
- Downhole Storage Wynona storage not in use. Primary storage of radioactive materials in Hominy. Wynona storage is ready if needed.
- 4. Storage Shields On the truck (one truck was in). Properly secured and labeled.

This completes my audit and I will visit Petro Dat. again on or about March 15, 1991 and I will forward you a report at that time.

Very truly yours,

Al Caswell

9101090093 9012**3**1 REG4 LIC30 35-23137-01 PDR

cc: Harold Haught

90-1904