William 5. Orser Senior Vice President

9101090239 9017

ADOCK 05000241

PDR

68

Detroit

Fermi 2 6400 North Dixle Highway Newport Michigan 48166 (313) 566-5201



December 27, 1990 NRC-90-0183

U. S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, D. C. 20555

References: 1) Fermi 2 NRC Docket No. 50-341 NRC License No. NPF-43

- Detroit Edison Letter to NRC, VP-NO-87-0051, dated April 2, 1987
- 3) NRC Letter, dated October 6, 1987
- Subject: Submittal the Detroit Edison Inservice Inspection-Wirlestructive Examination (ISI-NDE) Program - Revision 1, Change 0

Attached is the latest version of the Fermi 2 Inservice Inspection-Nondestructive Examination (ISI-NDE) Program, Revision 1, Change 0 dated Docember 7, 1990. This program document was previously submitted in Reference 2 as Revision 0, Change 2 and was reviewed and found acceptable as documented in the NRC Safety Evaluation contained in Reference 3. No changes have been made which require relief from Code requirements or NRC approval.

Revision 1, Change 0 of this program document incorporates the following changes:

- The entire document has been republished using a Detroit Edison in-house word processor.
- The title of the document was changed to Inservice Inspection-Nondestructive Examination (ISI-NDE) Program (Plan).
- The introduction was reworded to identify the commercial operation date and the fact that this program includes only components selected for inspection.

 Components were deleted from the program following removal from the plant.

USNRC December 27, 1990 NRC-90-0183 Page 2

- 5. Relief Requests RR-A5 and RR-A9 were revised to delete components deleted from the plant.
- 6. The definition of "period" was clarified.
- Outage codes were added and components for which inspections were completed or scheduled were identified in the tables.
- Additional welds required by NUREG-0313, Revision 2 and Generic Letter 88-01, including ANSI P31.1 piping welds, were added.
- The reactor pressure vessel internals listing and non-safety related/non-Technical Sp cification snubber listing were reformatted.
- Inspections for vessel bolting, reactor pressure vessel (RPV) lifting lugs, and RPV support skirt were added.
- 11. Notes 7-15 were added to ISI Program Table, Note 2 was revised, and reference to applicable notes was included in the Remarks column of the table for each component. The additional notes mostly address inspections added by General Electric SILS or NRC Information Notices and other issuances.
- The P&ID reference drawings were changed to new ISI Classification Boundary Drawings. The latest revisions of ISI-NDE isometrics are included.
- 13. Relief Request RR-C1 was deleted.
- Snubber listings were revised based on replacements, modifications and deletions during outages.
- 15. Snubbers in locked high radiation/neutron ares were reclassified as inaccessible.
- Code Cases N-308, N-62-4, and N-307-1 were added to Appendix F.
- Latest versions of documents were included in the appendices.
- 18. Miscellaneous typing and editorial corrections were made.

This revision is submitted for your information and does not constitute a 10 year program update as required by 10CFR50.55a. Please file this document for future reference. USNRC December 27, 1990 NRC-90-0183 Page 3

If you have any questions, please contact Ms. Lynne S. Goodman at (313) 586-4211.

sincerely.

10

7

Attachment

10

cc: A. B. Davis R. W. DeFayette W. G. Rogers J. F. Stang