JAAN 1919991

DCD

Docket No. 50-186

University of Missouri ATTN: Dr. J. Steven Morris Interim Director, Research Reactor Facility Research Park Columbia, MO 65201

Gentlemen:

This refers to the routine inspection conducted by Messrs. T. Ploski and D. Barss of this office on December 18-21, 1990, of activities at the University of Missouri Research Reactor Facility, authorized by NRC Operating License No. R-103 and to the discussion of our findings with Messrs. J. Sheridan, J. Rhyme, C. McKibben and others at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Robert Greger, Chief

Reactor Programs Branch

Enclosure: Inspection Report No. 50-186/90002(DRSS)

knowly

13307

DCD/DCB (RIDS) Q OC/LFDCB		PDR			IE35
Dr. William V of Nuclear RIII Amis For Ploski/lh 01/7/91 Ve3	ernetson, Dire Facilities RIII Om Barss/19/4 Yes	RIII Shell Shell 1/7/9/	200 RIII GO lo Jackiw 1-7-91	RILL	RIII Greger 1-9-9