

APPENDIX A

NOTICE OF VIOLATION

Ebasco Services, Incorporated
South Kearney, New Jersey 07032

Docket No. 030-05323
License No. 29-07056-03

As a result of the inspection conducted on December 11, 1990, and in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (Enforcement Policy) (1990), the following violations were identified:

- A. 10 CFR 34.33 requires, in part, that pocket dosimeters shall be checked at periods not to exceed one year for correct response to radiation.

Contrary to the above, as of December 11, 1990, pocket dosimeters 2727 and 2644E had not been checked for correct response to radiation for a period not to exceed one year. Specifically, pocket dosimeter 2727 and 2644E were used at a jobsite on January 17, 1990, and no record of response check was available.

This is a Severity Level IV violation. (Supplement VI)

- B. Condition No. 16 of License No. 29-07056-03 requires that the licensee shall conduct its program in accordance with the statements, representations and procedures contained in the application dated February 25, 1986.

1. Item No. 10.3 of the application dated February 25, 1986, Attachment No. 6., paragraph 3, requires audits of radiographers be performed at intervals not to exceed three months.

Contrary to the above, on September 28, 1990, radiography was performed at a jobsite in Vermont using 33 curies of cobalt-60 and the radiographer had not been audited since June 6, 1990.

2. Item No. 8 of the application dated February 25, 1986, Attachment No. 3, paragraph 7, requires that all radiographic personnel will participate in the periodic radiation safety training program at least once per year.

OFFICIAL RECORD COPY

ML DL EBASCO - 0003.0.0
01/08/91

9101220023 910109
REG1 LIC30
29-07056-03 PDR

RETURN ORIGINAL TO
REGION I

1E:07

Contrary to the above, as of December 11, 1990, periodic training had not been conducted since January 1, 1989.

These are Severity Level IV violations. (Supplement VI)

Pursuant to the provisions of 10 CFR 2.201, Ebasco Services, Inc. is hereby required to submit to this office within thirty days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.