

MISSISSIPPI POWER & LIGHT COMPANY Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205 November 9, 1982

JAMES P. McGAUGHY, JR. ASSISTANT VICE PRESIDENT

Office of Inspection & Enforcement U. S. Nuclear Regulatory Commission Region II 101 Marietta St., N.W., Suite 3100 Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station Unit 1 Docket No. 50-416 License No. NPF-13 File 0260/L-835.0

Fire Barrier Broken for Pulling Additional Cable Into Panel 1H13P614 (Special Report)

550 . .

w

Reference: LER 82-102/99 X-0 AECM-82/537

During Shutdown, while performing maintenance to pull additional cable into panel 1H13P614, a panel fire barrier was broken. This report is being submitted per T.S.3.7.7 and 6.9.2. Attached is LER 82-102/99 X-0.

Yours truly

FOR J. P. Mc baughy JR.

JPM: sap Attachment

cc: Mr. N. L. Stampley (w/a)

Mr. R. B. McGehee (w/o)

Mr. T. B. Conner (w/o)

Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a) Office of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Document Control Desk (w/a) U. S. Nuclear Regulatory Commission Washington, D. C. 20555

8211150295 821109 PDR ADDCK 05000416 IE 22