In Reply Refer To: License: General Licensee 10 CFR 150.20 Docket: 15000033/90-02

Midwest Industrial X+Ray, Inc. ATTN: Michael Manger, President P.O. Box 133 Fargo, North Dakota 58107

Gentlemen:

This refers to the routine, unannounced radiation safety inspection conducted by Mr. Selvan Rajendran of this office on November 28-29, 1990, of activities authorized by North Dakota Byproduct Material License No. 33-14907-01, and to the discussion of our findings held by the inspector with members of your staff at the conclusion of the inspection.

The inspection was an examination of activities conducted under the license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of the license. The inspection consisted of selective examinations of procedures and representative records, interviews of personnel, independent measurements, and observations by the inspector.

The inspector also observed a field site radiography at Williams Pipeline Company's shop at Alexandria, Minnesota, on November 29, 1990. The inspector noted that proper surveys were performed on the camera and the equipment, and radiation signs were posted at appropriate areas. The overall radiation safety program seemed to be adequately managed by your staff.

No violations or deviations were identified.

The inspector also reviewed actions you had taken with respect to the violations observed during our previous inspection conducted on August 10-11, 1989. He verified that corrective actions for the violations had been implemented.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter will be placed in the NRC Public Document Room.

*RIV:NMLS SRajendran *C:NMLS WLFisher D:DRSS AFFERACH

TE-07

*Previously Concurred

9101220104 910111 NMSS LIC30 33-14907-01 PDR Midwest Industrial X-Ray, Inc.

Should you have any questions concerning this letter, we will be pleased to discuss them with you.

-2+

Sincerely, Original Signed Dy.

A. B. BEACH

A. Bill Beach, Director Division of Radiation Safety and Safeguards

CC:

the maple

North Dakota Radiation Control Program Director Minnesota Radiation Control Program Director

bcc:

DMB - Original (IE-07) RDMartin ABBeach LAYandell MRodriguez, OC/LFDCB (4503) *WLFisher *CLCain *SRP endran *NhLJ *MIS System *RIV Files (2) *RSTS Operator *REHall, URFO JAGrobe, RIII

*W/766