

### COLBY-THIELMEIER TESTING COMPANY INC.

10627 LIBERTY STREET . ST. LOUIS, MO. (63132) . HA 7-0221

November 4, 1982 License No. 24-13737-01

U. S. Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, Illinois 60137

Re: Our safety inspection of 9-16-82.
Your letter dated 9-28-82.
Corrective procedures to prevent reoccurrence.

Dear Mr. Wiedeman,

We have taken the following corrective actions to remedy the citations we received during our safety inspection of 9-16-82. We have included a copy of the Appendix to your letter stating the specific violation and our proposed procedures for correction.

Appendix, Item 1. - Use of out of calibration date meters.

We to post a listing of in date survey meters at our radioactive materials vault door. This will permit the radiographer to check at a glance if his meter is calibration date. This list to be revised at each and every date change. We have included copies of these listings for your review. This procedure was placed in effect on 9-20-82.

Appendix, Item 2. - Failure to maintain monitoring records upon receipt of source.

During our inspection we discussed with Mr. D. R. Gibbons that we always surveyed a source upon receipt. We did not maintain a record of this as we did not understand that this was required. We use the shipping ticket which arrives with the source to keep records on that specific source by serial number. We suggested at the time of inspection that we would record our monitoring of received source on this shipping ticket. Mr. Gibbons was of the opinion that this would correct the violation. We received a source on 10-20-82, our first received since the inspection. The shipping container was monitored and the readings were recorded on the shipping ticket. A copy of this ticket is included for your review. We to continue this practice unless notified differently.

Our apologies for the noncompliance to our procedures. It is our desire to operate within the established rules and regulations. You will have our full cooperation in the attaining of our desires.

Respectfully, Colby-Thielmeier Testing Co., Inc.

2. 4. Thielmeier. Pres.

CC with attachments:

Mr. D. R. Gibbons, USNRC, Region III

## METERS IN DATE TO 1-5-83

2152

CALIBRATION Due 1-5-83

4489

1-5-83

343

1-18-83

1655

1-18-83

IF METER DON'T WORK Remove From List.

### METERS IN DATE To 10-26-82

828

CALIBRATION Due 10-26-82

4239

10-26-82-

2152

1-5-83

4489

1-5-83

343

1-18-83

1655

1-18-83

IF METER DON'T WORK Remove From List.

# METERS IN DATE TO 10-8-82

1655

CAlibration Due 10-8-82

2423

10-8-82

4848

10-8-82


828


10-26-82

4-239

10-26-82

IF METER DON'T WORK Remove From List.





SHIP-TO ADDRESS

ORIGINAL

COLBY THIELMEIER TEST. CO CUSTOMER 120800 COMPANY 1 10627 LIBERTY AVE. ST. LOUIS



MO 63132

SHIPPING CHARGES

\*\*\* ACCEPTS BACKORDER ORDER NO. REFERENCE ORDER DATE ORDER TYPE \*\*\* ACCEPTS PARTIAL SHIP

C043797 THIELMEIER 10/19/82 PREPAID COLLECT PREPAY

SHIP INSTRUCTIONS - FEDERAL EXPRESS COLLECT

PACK CODE LOCATION

ITEM NUMBER QUANTITY ORDERED

U/M

QUANTITY SHIPPED

CI 100

2 8018001003 IR-192 SOURCE, MODEL A-2-A 102 SOURCE SERIAL NO. 82 102 SOURCE SIZE -/X 0 9 SHIP IN C-10 S/N -//9

OO SRC TUBE ASSY 3/8 METAL 7 FT 8111003005

Meter 4489 10-20-89 45 MR/AR AT SURFACE 3 MR/hR AT I meter 8.3.0,

Placed in 1964 - 10-25-82 -3, 0.