

Process Technology North Jersey

Subsidiary of RTI Inc.

108 LAKE DENMARK ROAD, ROCKAWAY, NJ 07866
(201) 625-8400 • FAX: (201) 625-7820

May 15, 1989

Mr. John White, Chief
Nuclear Materials Safety Section C
United States Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, Pennsylvania 19406

License No. 29-13613-02


Dear Mr. White:

This is to confirm and document our understanding regarding the Ludlum subsystem monitor mentioned in our letter of April 8, 1988. This subsystem was originally used in the old fully automatic conveyor system to prevent the inadvertent automatic carrying out of radioactive material to an uncontrolled area.

When the carrier system was changed to a manual system this ludlum monitor was no longer required. Due to a typographical error it was not deleted from the license amendment.

On August 1, 1988, prior to start up, Laurence F. Friedman, Ph.D, C.H.P. of your office conducted a special safety inspection. At that time we discussed with him the Ludlum subsystem monitor and it was agreed that the Ludlum subsystem was not required and we could operate without it. Reference your letter of Sept. 2, 1988 to Tass Varaklis, VP.

Sincerely,





John Russen RSO

cc
J. Scandalios
No. J. RSO file

B119

Process Technology
North Jersey
Subsidiary of RTI Inc.
108 LAKE DENMARK ROAD
ROCKAWAY, NJ 07866



Mr. John White, Chief
Nuclear Materials Safety Section C
United States Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

