

Florida Power

November 15, 1982 #3F-1182-13 File: 3-0-3-a-1

Mr. James P. O'Reilly Regional Administrator, Region II U.S. Nuclear P gulatory Commission Office of Inspection & Enforcement 101 Marietta St. N.W., Suite 3100 Atlanta, Ga. 30303

Subject:

Crystal River Unit 3 Docket No. 50-302

Operating License No. DPR-72

Licensee Event Report No. 81-031, Rev. 1

Dear Mr. O'Reilly:

Enclosed please find Licensee Event Report No. 81-031, Rev. 1, and the attached supplementary information sheet, which are submitted in accordance with Technical Specification 6.9.8.1.h. This report is a follow-up of our report to Mr. J. P. O'Reilly dated November 2, 1982.

Should there be any questions, please contact this office.

Very truly yours,

P. Y. Baynard

Assistant to Vice President

Jary y Barnaul

Nuclear Operations

PGH/mlg

Enclosure

cc: Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

8211170266 821115 PDR ADDCK 05000302 PDR PDR JE22